

STATE OF WASHINGTON DEPARTMENT OF ECOLOGY

3100 Port of Benton Blvd • Richland, WA 99354 • (509) 372-7950
711 for Washington Relay Service • Persons with a speech disability can call 877-833-6341

August 19, 2014

14-NWP-176

Mr. Rudy Guercia U.S. Department of Energy 825 Jadwin Avenue, MSIN: A3-04 Richland, Washington 99352

Re: Transmittal of Signed Facility Status Change Form for 100-N Ancillary Facilities

Dear Mr. Guercia:

Enclosed is the originally signed Facility Status Change Form for Facility ID: 100-N AOC Area 8, Control # D4-100N-0065.

need aden

If you have any questions, please contact me at kim.welsch@ecy.wa.gov or (509) 372-7882.

Sincerely,

Kim Welsch, Acting Project Manger

Environmental Restoration

Nuclear Waste Program

tkb

Enclosure

cc w/enc:

NWP Central File

cc w/o enc:

NWP Reader File

AUG 2 0 2014

DOE-RLCC

FACILITY STATUS CHANGE FORM

Date S	Submitted:	Area:	Control #:	
8-6-2014 Originator: Dan Saueressig Phone: 509-521-5326		100-N Facility ID: 100-N AOC Area 8 Action Memorandum:	D4-100N-0065	
			DT-10011-0000	
			*	
This form documents agreement among the parties listed below on the status of the facility D&D operation				
	the disposition of under	lying soil in accordance with the a	applicable regulatory decision documents.	
Section	n 1: Facility Status	9		
\boxtimes	* # **			
 All D4 operations required by action memo complete. D4 operations required by action memo partially complete, remaining operations deferred. 				
u	1 24 operations required by action memo partially complete, remaining operations deterred.			
Descri	ption of Completed Acti	vities and Current Conditions:		
Facility House, The are	, 151-N Electrical Substati	ion, 153-N Electrical Switchgear Buil Iter Plant, 183-N Water Treatment Pl existing grade.	-ND Remote Air Intake, 108-N Chemical Unloading ding, 182-N High Lift Pumphouse, 184-N Power ant and the 185-N HGP Turbine Generator Plant).	
		waste site(s) present. Cleanup and closeout to be addressed under Record of Decision.		
	Potential waste site discovered during D4 operations. Waste site identification number <to be=""> assigned.</to>			
	Cleanup and closeout to be addressed under Record of Decision.			
Doscri	otion of Current/As-Left	Canditions		
The 100 access/ Electric Demine been ba Identifi	O-N AOC Area 8 consists of the entry to the facilities in the all Substation, 153-N Electralized Water Plant, 183-Packfilled to existing grade.	of a large area south and east of the e vicinity (105-ND Remote Air Intake, trical Switchgear Building, 182-N Hig N Water Treatment Plant and the 185	109-N Heat Exchanger Building and provided 108-N Chemical Unloading Facility, 151-N h Lift Pumphouse, 184-N Power House, 163-N 5-N HGP Turbine Generator Plant). The area has Waste Site Discovery (as applicable): of adjacent waste sites.	
Section	3: List of Attachments			
	Determination Form SDF			
V	2/		8/7/14	
DOE-RI	Thy Well.	EPA Ecology	Date 18 14 Date	

FACILITY STATUS CHANGE FORM

DISTRIBUTION:

EPA: Dennis Faulk, B1-46
Ecology: Wanda Elliott, H0-57
DOE: Rudy Guercia, A3-04
Document Control, H4-11 H0-30
Administrative Record, H6-08 100-NR-1 OU

SIS Coordinator: Benjamin Cowen, H4-22

D4 EPL: Chris Strand, L4-45

Sample Design/Cleanup Verification: Theresa Howell, H4-23

FR Engineering: Rich Carlson, H4-22 FR EPL: Dan Saueressig, X8-02

100-N ANCILLARY FACILITIES REMOVAL ACTION SAMPLING DETERMINATION FORM

Determination Number SDF-100N-039

A. INSTRUCTIONS

This form must be completed to: 1) document existing data in order to determine if current data is suitable to prove completion of 100-N Ancillary Facilities, or 2) document that site-specific sampling and analyses are needed to provide completion for 100-N Ancillary Facilities.

B. GENERAL INFORMATION

Building Name: 100-N AOC Area 8

Building Number: N/A

WIDS Sites Associated or Adjacent:

Historical information reviewed indicates AOC Area 8 functioned primarily as a roadway and asphalted access area to various support buildings south of the 109-N Heat Exchanger. The building footprints and waste sites within AOC Area 8 have their own closure documents [Facility Status Change Forms for ancillary facilities and Remaining Sites Verification Packages (RSVPs) for waste sites]. Some waste sites do not have approved RSVPs in place, however backfill concurrence forms have been approved allowing backfill of the sites while the RSVPs are finalized.

100-N-8, 108-N Facility, 108-N CUF, Rejected, WSRF No. 2000-050.

100-N-10, 120-N-5 Facility Liquid Unplanned Release 2 (09/02/87), Rejected, WSRF No. 2000-052.

100-N-11, 120-N-5 Transfer Trench Liquid Unplanned Release 3, Rejected, WSRF No. 2000-053.

100-N-23, Resin Disposal Pit Liquid Waste Site 1, Interim Closed Out, RSVP-2013-009, WSRF No. 2013-009, Transmittal Letter dated August 6, 2013 (CCN 172204).

100-N-27, 108-N Sump, 108-N Neutralization Pit, Rejected, WSRF No. 2000-054.

100-N-58, South Pond, 120-N South Settling Pond, 1324-N South Settling Pond, Accepted, Closed Out, CVP-2001-00021, WSRF No. 2001-093.

100-N-84:1, 100-N Area Raw Water Pipelines, No Action, RSVP-2010-019, WSRF No. 2010-019, Transmittal Letter dated December 12, 2012 (CCN 169002).

100-N-84:3, 100-N Area Filtered and Potable Water Pipelines, No Action, RSVP-2010-020, WSRF No. 2010-020, Transmittal Letter dated November 14, 2012 (CCN 168594).

100-N-84:4, 100-N Area Steam and Condensate Pipelines, Accepted.

100-N-84:5, 100-N Area Sanitary Pipelines, Accepted.

100-N-84:6, 100-N Area Chemical and Process Sewer Pipelines, Accepted.

100-N-84:7, 100-N Area Unidentified and Other Miscellaneous Pipelines, No Action, RSVP-2011-092, WSRF No. 2011-092, Transmittal Letter dated May 30, 2012 (CCN 165808).

100-N-84:9, 100-N Area Active Raw Water Pipelines, No Action, RSVP-2010-019, WSRF No. 2012-012, Transmittal Letter dated December 12, 2012 (CCN 169002).

100-N-103:1, 100-N Steam Condensate French Drains (inactive), Accepted, No Action, RSVP-2011-114, WSRF No. 2011-114, Transmittal Letter dated 7/30/2012 (CCN 166823).

116-N-8, 163-N Mixed Waste and Hazardous Waste Container Storage Pad, 1330-N, 116-N-8 Storage Pad, Rejected, WSRF No. 2000-035.

120-N-2, 1324-N Surface Impoundment, Accepted.

120-N-5, 108-N/163-N Transfer Line and Neutralization Pit, Rejected, WSRF No. 2000-096.

100-N ANCILLARY FACILITIES REMOVAL ACTION SAMPLING DETERMINATION FORM

Determination Number SDF-100N-039

Other:

Buildings within or near AOC Area 8 include the 105-ND Remote Air Intake, 108-N Chemical Unloading Facility, 151-N Electrical Substation, 153-N Electrical Switchgear Building, 163-N Demineralized Water Plant, 183-N/NA/NB/NC/ND/NE/NF Water Treatment Plant and support buildings, the 1330-N Waste Storage Facility, 1802-N Pipe Trestle, the 1900-N Water Supply Tanks and the 182-N High Lift Pumphouse. All wells within 10 feet from AOC Area 8 have been decomissioned.

decomissioned.	All wells within to leet from AOC Area 8 have been
C. INFORMATION SOURCES	
Available information (list document number for each if app	plicable):
Historical Site Assessment: N/A	Site Walkdown: See Attachment 3
IH Characterization Report: N/A	Radiological Survey: See Attachment 4
IHC/FHC Document: N/A	WIDS/SIS: See Section B above.
PDSR: N/A	Facility Inspection: Visual Inspection (Attachment 3)
Waste Characterization Checklist: N/A	Summary Report: N/A
Other:	
D. HAZARDOUS SUBSTANCES	
Check all that apply:	
None ☐ Asbestos containing material ☐ Le	ead PCBs/PCB Articles Oils/Greases
Chemicals List:	ead PCBs/PCB Articles Oils/Greases
Radiological Contamination	S
☐ Other:	•
References/Comments:	
Liquids: Yes No	
If yes, describe source and nature of liquids:	
Were the hazardous substances removed from the facility p	rior to demolition?
As verified by what documentation:	
The AOC is not a facility. Surrounding facilities have their ow	ın FSCFs.
Was there potential for hazardous substances to be introducted during facility operations or demolition?	ced into the soils ☐ Yes ☒ No ☐ N/A
References/Comments: /isual inspection performed (Attachment 3) confirming no sta	aining or other anomalous conditions observed.
List any hazardous materials left in the building for demolitio N/A	n:
Does review of historical records and process knowledge inc to be present in the facility? No	ficate a potential for radiological or chemical contamination
Comments:	
E. FIELD OBSERVATIONS	
Visual Inspection	

Acrobat 9.0

100-N ANCILLARY FACILITIES REMOVAL ACTION **Determination Number** SAMPLING DETERMINATION FORM SDF-100N-039 Were any stained soils/anomalies discovered during or after demolition of the facility? ☐ Yes X No References/Comments: Were samples taken of the stained soils/anomalies? Yes No N/A References/Comments: Do results of the samples indicate that chemical contamination exists? ☐ Yes No N/A References/Comments: Is the area potentially a discovery site? Yes X No References/Comments: Radiological Surveys Did radiological surveys (GPERS or equivalent) identify contamination? ⊠ No ☐ Yes References/Comments: Radiological surveys of AOC Area 8 for gamma contamination using GPERS identified no contamination greater than 1.5 x background. A composite diagram of the survey is presented in Attachment 4. In addition, numerous in-process hand held surveys never indicated that radiological contamination was discovered south of the reactor or within the Field Remediation waste sites in AOC Area 8. Were samples taken of the radiologically contaminated soils? ☐ Yes ☐ No N/A References/Comments: Is the area potentially a discovery site? ☐ Yes X No References/Comments: Were the contaminated materials removed? ☐ Yes No N/A References/Comments: F. WIDS SITES Were there any WIDS sites affected by D4 activities? Yes X No If yes, list the WIDS sites: Were the WIDS site(s) completely removed? X Yes □ No References/Comments: See waste site data in Section B of this Sampling Determination Form. Will the Ancillary Facility Footprint be deferred to FR to be closed out with a co-located Waste Site? Yes References/Comments: G. COPCs FOR SOILS AND STRUCTURES REMAINING AFTER DEMOLITION What are the potential contaminants of concern for the remaining below-grade soil? ☐ VOC ☐ Metals None None SVOC TPH PCBs Rad Other (Specify):

Acrobat 9.0

100-N ANCILLARY FACILITIES REMOVAL ACTION **Determination Number** SAMPLING DETERMINATION FORM SDF-100N-039 Comments: Summary of in-process soil sampling requirements: N/A Constituents detected / concentrations / rationale N/A Sample Collection Summary N/A H. NOTES / ADDITIONAL INFORMATION Check here if additional information / data / maps / sketches are attached to this form. If checked, list the attachment(s): Attachment 1. Photographs or AOC Area 8 Attachment 2. WIDS sites and wells around AOC Area 8 Attachment 3. Visual Inspection of 100-N AOC Area 8 Attachment 4. Global Positioning Environmental Radiological Surveyor (GPERS) survey of AOC Area 8 I. SAMPLING Are soil samples required to demonstrate that remaining structure or below-grade X No Yes soils meet cleanup standards? Based on the above information it was determined that sampling: Will will not be required in order to demonstrate that cleanup criteria have been met. The individual below acknowledges that the review of this facility has been completed. He or she also commits to provide to the Department of Energy (DOE) and the Washington State Department of Ecology (Ecology) any available information that could alter the sampling decision established in this form. Printed Name Information Reviewer Signature Date Dan Saueressio 8/6/14 The regulatory representative below agrees with the decision outlined in section I of this form for the indicated facility and supports implementation of that decision based on the information currently available.

Printed Name

Rudy Guercia

Printed Name

KIM WELSOH

DOE Signature

Signature

Date

Date